

APPENDIX 6.4

Photographic Record

Appendix 6.4 Photographic Record

List of plates

Plate 6.1 A dense sward of *Juncus effusus* has developed in areas where peat was deposited in recent years. This area was dominated by cutover bog prior to the start of peat deposition.

Plate 6.2 Another view of a peat deposition area dominated by a dense sward of *Juncus effusus*.

Plate 6.3 Small area of *Eriophorum angustifolium*) with a good cover of *Sphagnum cuspidatum* at the north end of Bay 3

Plate 6.4 A general view of the cutover blanket bog surface which dominates Bay 2. Viewed from the southern end of Bay 2, looking in a north-easterly direction

Plate 6.5 Occasional fragments of re-colonising vegetation, dominated by *Juncus effusus* are characteristic of the survey area

Plate 6.6 Wet ditches occur throughout the area in association with the high field areas

Plate 6.7 In Bay 6 wet grassland dominated by *Juncus effusus* is dominant

Plate 6.8 New road alongside the main stream near to site

Plate 6.9 New pond area created by damming of the main stream

Plate 6.10 As at 6.9

Plate 6.11 Burnt area to west of site

Plate 6.12 Burnt area at burrow systems

Plate 6.13 Former peat railway track

Plate 6.14 View of Area 6

Plate 6.15 Main stream at north

Plate 6.16 Scrub alongside stream at north.

Plate 6.17 Settlement ponds

Plate 6.18 Southern section of the site facing eastwards with nearby conifer plantation

Plate 6.19 Lined drain at the southern end of the site

Plate 6.20 Degraded Atlantic Blanket bog close to the site boundary



Plate 6.1 A dense sward of *Juncus effusus* has developed in areas where peat was deposited in recent years. This area was dominated by cutover bog prior to the start of peat deposition



Plate 6.2 Another view of a peat deposition area dominated by a dense sward of *Juncus effusus*.



Plate 6.3 Small area of *Eriophorum angustifolium*) with a good cover of *Sphagnum cuspidatum*



Plate 6.4 A general view of the cutover blanket bog surface which dominates Bay 2. Viewed from the southern end of Bay 2, looking in a north-easterly direction



Plate 6.5 Occasional fragments of re-colonising vegetation, dominated by *Juncus effusus* are characteristic of the survey area



Plate 6.6 Wet ditches occur throughout the area in association with the high field areas



Plate 6.7 In Bay 6 wet grassland dominated by *Juncus effusus* is dominant



Plate 6.8 New road alongside the main stream near to site



Plate 6.9 New pond area created by damming of the main stream



Plate 6.10 As at 6.9



Plate 6.11 Burnt area to west of site



Plate 6.12 Burnt area at burrow systems



Plate 6.13 Former peat railway track



Plate 6.14 View of Area 6



Plate 6.15 Main stream at north



Plate 6.16 Scrub alongside stream at north.



Plate 6.17 Settlement ponds



Plate 6.18 Southern section of the site facing eastwards with nearby conifer plantation



Plate 6.19 Lined drain at the southern end of the site



Plate 6.20 Degraded Atlantic Blanket bog close to the site boundary